# HL-334AB




| REF: | PART NO: | PART DESCRIPTION |
|---|---|---|
| | | |
| 3 | * 179-55 | BODY CHANNEL WELCH PLUG |
| 9 | + * 16B-217 | DIAPHRAGM GASKET |
| 10 | + * 237-600 | DIAPHRAGM |
| 11 | 91A-275 | **DIAPHRAGM** COVER |
| 13 | + * 16B-223 | FUEL PUMP GASKET |
| 14 | + * 237-141 | FUEL PUMP DIAPHRAGM |
| 15 | 141-89 | FUEL PUMP BODY |
| 16 | 15C-51 | FUEL PUMP BODY SCREW(6) |
| 17 | 95-170 | FUEL STRAINER SCREEN |
| 18 | * 16B-205 | FUEL STRAINER COVER GASKET |
| 19 | 91A-351 | FUEL STRAINER COVER |
| 20 | 15B-313 | FUEL STRAINER COVER RETAINING SCREW |
| 21A | 43-388 | IDLE MIXTURE SCREW |
| 21B | 24B-449 | IDLE MIXTURE SCREW SPRING |
| 21C | 78A-256 | IDLE MIXTURE SCREW WASHER |
| 21D | 44-270 | IDLE MIXTURE SCREW PACKING |
| 23 | 15C-9 | IDLE SPEED SCREW |
| 24 | 24B-131 | IDLE SPEED SCREW SPRING |
| 25 | * 155A-27 | INLET CONTROL LEVER |
| 26 | 15B-329 | INLET CONTROL LEVER FULCRUM SCREW |
| 26A | 32-79 | INLET CONTROL LEVER FULCRUM PIN |
| 27 | * 233-710 P | INLET NEEDLE & SEAT SET |
| 28 | * 16B-199 | INLET SEAT GASKET |
| 29 | 24B-299 | INLET TENSION SPRING |
| 30A | 43-967 | HIGH SPEED MIXTURE SCREW |
| 30B | 24B-449 | HIGH SPEED MIXTURE SCREW SPRING |
| 30C | 78A-256 | HIGH SPEED MIXTURE SCREW WASHER |
| 30D | 44-270 | HIGH SPEED MIXTURE SCREW PACKING |
| 31 | 363-503 | NOZZLE CHECK VALVE |
| 33 | 29-224 | THROTTLE SHAFT CLIP |
| 35 | 15C-19 | THROTTLE SHAFT CLIP RETAINING SCREW |
| 36 | 24B-381 | THROTTLE SHAFT RETURN SPRING |
| 37 | 14-407 | THROTTLE SHUTTER |
| 38 | 15C-29 | THROTTLE SHUTTER SCREW |
| 39 | 13-1894 | THROTTLE SHAFT & LEVER |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | RK-117HL | REPAIR KIT |
| | DG-1HL | DIAPHRAGM & GASKET SET |
| | | |
| | * | INDICATES CONTENTS OF REPAIR KIT |
| | + | INDICATES CONTENTS OF DIAPHRAGM & |
| | | GASKET SET. |

www.tillotson-racing.com

Tillotson.

TILLOTSON LTD.
CLASH INDUSTRIAL ESTATE,
TRALEE, CO. KERRY,
IRELAND.